

CAMSHAFT ACTUATOR

FORD/LINCOLN/MERCURY 4.6L & 5.4L ENGINES

FORD	4.6-8	(281) SOHC	2006-10	Explorer	FORD	5.4-5 (330) SOHC	2005-10	F250 S.D.
FORD	4.6-8	(281) SOHC	2007-10	Sport Trac	FORD	5.4-5 (330) SOHC	2005-10	F350 S.D.
FORD	4.6-8	(281) SOHC	2009-10	F150	FORD	5.4-5 (330) SOHC	2005-10	Lobo
FORD	4.6-H	(281) SOHC	2005-10	Mustang	LINCOLN	5.4-5 (330) SOHC	2006-08	Mark LT
FORD	5.4-5	(330) SOHC	2005-14	Expedition	LINCOLN	5.4-5 (330) SOHC	2005-14	Navigator
FORD	5.4-5,V	(330) SOHC	2004-10	F150	MERCURY	4.6-8 (281) SOHC	2006-10	Mountaineer



Part number
G58422NS
UPC: 709523594231

PCI (Preferred Components, Inc.) tests every single tensioner to be sure they all are functioning properly. Chains meet load standards and OEM profile requirements. Guide rails are all 100% profile matched to OEM chain paths for exacting positions to provide proper camshaft valve timing. PCI is unparalleled in quality, dependability, and fit. This is done by controlling the quality in the USA where we do all of our own testing, developing, and in-depth cataloging research of OEM applications.

**** Always consult the PCI catalog listings for detailed application and fitment information****