

NEW CAMSHAFT ACTUATOR FOR GM 2.0L & 2.4L ECOTEC ENGINES

BUICK	2.0-V	(122)	2011-13	Regal	Pontiac	2.0-X	(122)	2007-09	Solstice
BUICK	2.0-V	(122)	2013-16	Verano	Pontiac	2.4-B	(145)	2007-08	G5
BUICK	2.4-C	(145)	2010	LaCrosse	Pontiac	2.4-B,0	(145)	2006-10	G6
CHEVROLET	2.0-X	(122)	2008-10	Cobalt	Pontiac	2.4-B	(145)	2006-09	Solstice
CHEVROLET	2.0-X,M	(122)	2008-10	HHR	Saab	2.0	(122)	2011	9-5
CHEVROLET	2.4-B	(145)	2006-08	Cobalt	Saturn	2.0-X	(122)	2007-10	Sky
CHEVROLET	2.4-W	(145)	2010	Equinox	Saturn	2.4-5,B	(145)	2007-09	Aura
CHEVROLET	2.4-P,V,U	(145)	2006-11	HHR	Saturn	2.4-B	(145)	2006-07	Ion
CHEVROLET	2.4-0,1,5,B,U,Z	(145)	2008-12	Malibu	Saturn	2.4-B	(145)	2007-10	Sky
GMC	2.4-W	(145)	2010	Terrain	Saturn	2.4-P,Z,1	(145)	2008-10	Vue



Intake

Part number

G58218

UPC: 709523582184

PCI (Preferred Components, Inc.) tests every single tensioner to be sure they all are functioning properly. Chains meet load standards and OEM profile requirements. Guide rails are all 100% profile matched to OEM chain paths for exacting positions to provide proper camshaft valve timing. PCI is unparalleled in quality, dependability, and fit. This is done by controlling the quality in the USA where we do all of our own testing, developing, and in-depth cataloging research of OEM applications.

**** Always consult the PCI catalog listings for detailed application and fitment information****