

**NEW CAMSHAFT ACTUATOR FOR
GM 6.0L & 6.2L OHV ENGINES**

CADILLAC	6.2-8 (376)	2007-08	Escalade	GMC	6.0-Y (364)	2007-09	Sierra 1500
CADILLAC	6.2-8 (376)	2007-08	Escalade ESV	GMC	6.0-Y (364)	2007-09	Yukon XL
CADILLAC	6.2-8 (376)	2007-08	Escalade EXT	GMC	6.2-8 (376)	2007-08	Sierra 1500
CHEVROLET	6.0-Y (364)	2007-09	Avalanche	GMC	6.2-8 (376)	2007-08	Yukon XL
CHEVROLET	6.0-Y (364)	2007-09	Silverado 1500	GMC	6.2-8 (376)	2007-08	Yukon
CHEVROLET	6.0-Y (364)	2007-09	Suburban 1500	HUMMER	6.2-8 (376)	2008	H2



Part number
G58425
UPC: 709523584256

PCI (Preferred Components, Inc.) tests every single tensioner to be sure they all are functioning properly. Chains meet load standards and OEM profile requirements. Guide rails are all 100% profile matched to OEM chain paths for exacting positions to provide proper camshaft valve timing. PCI is unparalleled in quality, dependability, and fit. This is done by controlling the quality in the USA where we do all of our own testing, developing, and in-depth cataloging research of OEM applications.

**** Always consult the PCI catalog listings for detailed application and fitment information****