

**NEW CAMSHAFT ACTUATOR FOR  
GM 4.3L OHV ENGINES**

<b>CHEVROLET</b>	<b>4.3-P (262)</b>	<b>2018-20</b>	<b>OHV</b>	<b>Express 2500</b>
<b>CHEVROLET</b>	<b>4.3-P (262)</b>	<b>2018-20</b>	<b>OHV</b>	<b>Express 3500</b>
<b>CHEVROLET</b>	<b>4.3-H (262)</b>	<b>2014-18</b>	<b>OHV</b>	<b>Silverado 1500</b>
<b>GMC</b>	<b>4.3-P (262)</b>	<b>2018-20</b>	<b>OHV</b>	<b>Savana 2500</b>
<b>GMC</b>	<b>4.3-P (262)</b>	<b>2018-20</b>	<b>OHV</b>	<b>Savana 3500</b>
<b>GMC</b>	<b>4.3-H (262)</b>	<b>2014-18</b>	<b>OHV</b>	<b>Sierra 1500</b>



**Part number**

**G58240**

**UPC: 709523582405**

*PCI (Preferred Components, Inc.) tests every single tensioner to be sure they all are functioning properly. Chains meet load standards and OEM profile requirements. Guide rails are all 100% profile matched to OEM chain paths for exacting positions to provide proper camshaft valve timing. PCI is unparalleled in quality, dependability, and fit. This is done by controlling the quality in the USA where we do all of our own testing, developing, and in-depth cataloging research of OEM applications.*

**\*\* Always consult the PCI catalog listings for detailed application and fitment information\*\***