

NEW CAMSHAFT ACTUATOR FOR GM 5.3L & 6.2L OHV ENGINES

CAD 6.2-J (376) 2015-20 Escalade	CHEV 6.2-J (376) 2019-20 Tahoe
CHEV 6.2-7 (376) 2016-21 Camaro	GMC 5.3-C (325) 2014-19 Sierra 1500
CHEV 6.2-7 (376) 2014-19 Corvette	GMC 5.3-R (325) 2016-18 Sierra 1500
CHEV 5.3-C (325) 2014-19 Silverado 1500	GMC 6.2-J (376) 2015-18 Sierra 1500
CHEV 5.3-R (325) 2016-18 Silverado 1500	GMC 5.3-C (325) 2015-20 Yukon
CHEV 6.2-J (376) 2014-18 Silverado 1500	GMC 6.2-J (376) 2015-20 Yukon
CHEV 5.3-C (325) 2015-20 Suburban	GMC 5.3-C (325) 2015-20 Yukon XL
CHEV 6.2-J (376) 2019-20 Suburban	GMC 6.2-J (376) 2015-20 Yukon XL
CHEV 5.3-C (325) 2015-20 Tahoe	

- VVT Oil Control Valve Can Not Be Reused And Must Be Replaced Upon Re-Assembly
- Order Oil Control Valve Separately As Needed
- For 6.2L Applications Applies To Non ZR1

Qty 1 Required

Part number

G58359

UPC: 709523583594



PCI (Preferred Components, Inc.) tests every single tensioner to be sure they all are functioning properly. Chains meet load standards and OEM profile requirements. Guide rails are all 100% profile matched to OEM chain paths for exacting positions to provide proper camshaft valve timing. PCI is unparalleled in quality, dependability, and fit. This is done by controlling the quality in the USA where we do all of our own testing, developing, and in-depth cataloging research of OEM applications.

**** Always consult the PCI catalog listings for detailed application and fitment information****