


NEW TIMING CHAIN TENSIONER HYUNDAI/KIA 1.6L DOHC ENGINES

HYUNDAI 1.6-E (1591cc) DOHC	2012-17	Accent	KIA 1.6-3 (1591cc) DOHC	2014-16	Forte Koup
HYUNDAI 1.6-3 (1591cc) DOHC	2018-19	Accent	KIA 1.6-3 (1591cc) DOHC	2014-18	Forte5
HYUNDAI 1.6-B (1591cc) DOHC	2017-21	Elantra	KIA 1.6-1 (1591cc) DOHC	2016-20	Optima
HYUNDAI 1.6-C (1591cc) DOHC	2018-20	Elantra GT	KIA 1.6-3 (1591cc) DOHC	2012-17	Rio
HYUNDAI 1.6-5 (1591cc) DOHC	2018-21	Kona	KIA 1.6-B (1591cc) DOHC	2018-19	Rio
HYUNDAI 1.6-A (1591cc) DOHC	2015-19	Sonata	KIA 1.6-2 (1591cc) DOHC	2021	Seltos
HYUNDAI 1.6-2 (1591cc) DOHC	2016-18	Tucson	KIA 1.6-A (1591cc) DOHC	2017-19	Soul
HYUNDAI 1.6-B (1591cc) DOHC	2019-21	Veloster	KIA 1.6-F (1591cc) DOHC	2020-22	Soul
HYUNDAI 1.6-D (1591cc) DOHC	2012-17	Veloster	KIA 1.6-2 (1591cc) DOHC	2014-19	Soul
HYUNDAI 1.6-E (1591cc) DOHC	2013-17	Veloster	KIA 1.6-5 (1591cc) DOHC	2012-13	Soul
KIA 1.6-C (1591cc) DOHC	2020-24	Forte			



Qty Req: 1

Part number

T66269

UPC: 709523662695

PCI (Preferred Components, Inc.) tests every single tensioner to be sure they all are functioning properly. Chains meet load standards and OEM profile requirements. Guide rails are all 100% profile matched to OEM chain paths for exacting positions to provide proper camshaft valve timing. PCI is unparalleled in quality, dependability, and fit. This is done by controlling the quality in the USA where we do all of our own testing, developing, and in-depth cataloging research of OEM applications.

**** Always consult the PCI catalog listings for detailed application and fitment information****