

NEW TIMING CHAIN GUIDE LINING

FORD/MAZDA 3.0L DOHC ENGINES

FORD	3.0-1 (181) DOHC	2006-09	Fusion
FORD	3.0-G (181) DOHC	2010-12	Fusion
LINCOLN	3.0-1 (181) DOHC	2006	Zephyr
MAZDA	3.0-D (181) DOHC	2003-08	6
MERCURY	3.0-1 (181) DOHC	2008	Mariner
MERCURY	3.0-G (181) DOHC	2009-11	Mariner
MERCURY	3.0-1 (181) DOHC	2006-09	Milan
MERCURY	3.0-G (181) DOHC	2010-11	Milan



For right hand & left hand timing chains
Replaces R78003

Qty Req: 2

Part number

R76141P

UPC: 709523751412

PCI (Preferred Components, Inc.) tests every single tensioner to be sure they all are functioning properly. Chains meet load standards and OEM profile requirements. Guide rails are all 100% profile matched to OEM chain paths for exacting positions to provide proper camshaft valve timing. PCI is unparalleled in quality, dependability, and fit. This is done by controlling the quality in the USA where we do all of our own testing, developing, and in-depth cataloging research of OEM applications.

**** Always consult the PCI catalog listings for detailed application and fitment information****