

**NEW TIMING KIT  
FOR GM 5.3L & 6.2L OHV ENGINES**

<b>CHEVROLET</b>	<b>5.3-C (325)</b>	<b>2015-18</b>	<b>Suburban</b>	<b>CHEVROLET</b>	<b>6.2-6,7 (376)</b>	<b>2016-18</b>	<b>Camaro</b>
<b>GMC</b>	<b>5.3 (325)</b>	<b>2014-18</b>	<b>Sierra (Mexico)</b>	<b>CHEVROLET</b>	<b>6.2-6,7,9 (376)</b>	<b>2014-19</b>	<b>Corvette</b>
<b>GMC</b>	<b>5.3-C (325)</b>	<b>2015-18</b>	<b>Yukon</b>	<b>CHEVROLET</b>	<b>6.2-J (376)</b>	<b>2014-18</b>	<b>Silverado 1500</b>
<b>CADILLAC</b>	<b>6.2-6 (376)</b>	<b>2016-18</b>	<b>CTS</b>	<b>CHEVROLET</b>	<b>6.2-J (376)</b>	<b>2018</b>	<b>Tahoe</b>
<b>CADILLAC</b>	<b>6.2-J (376)</b>	<b>2015-18</b>	<b>Escalade</b>				



DOES NOT INCLUDE CAMSHAFT SPROCKET

**Part number  
TS10361**

**UPC: 709523103617**

Componet	UPC	Description	Qty
<b>C1360</b>	709523013602	Timing Chain	1
<b>G56067</b>	709523560670	Crankshaft Sprocket	1
<b>T66273</b>	709523662732	Timing Chain Tensioner	1

*PCI (Preferred Components, Inc.) tests every single tensioner to be sure they all are functioning properly. Chains meet load standards and OEM profile requirements. Guide rails are all 100% profile matched to OEM chain paths for exacting positions to provide proper camshaft valve timing. PCI is unparalleled in quality, dependability, and fit. This is done by controlling the quality in the USA where we do all of our own testing, developing, and in-depth cataloging research of OEM applications.*

**\*\* Always consult the PCI catalog listings for detailed application and fitment information\*\***